

PROGRAM ADMINISTRATOR DEPARTMENT ALECP INTERTEK 3933 U.S. ROUTE 11 CORTLAND, NY 13045-0950

OCEM Airfield Technology a division of Energy Technology S.r.l. Via 2 Agosto 1980, 11 40016 San Giorgio di Piano Bologna - Italy ORIGINAL ISSUE DATE: September 30, 2013

Recertification due: <u>July 2021</u>

An Activity Sponsored and Administered by Intertek

AIRPORT LIGHTING EQUIPMENT CERTIFICATION PROGRAM

CERTIFICATE OF CONFORMANCE

The product described below is hereby approved for listing in the next issue of the Federal Aviation Administration (FAA) Advisory Circular (AC) 150/5345-53, Appendix 3 Addendum "Airport Lighting Equipment Certification Program. The approval is based on successful completion of tests in accordance with the specifications listed in, and the requirements for approval described in the Advisory Circular, and the reporting to the Program Administrator the results of such tests, accompanied by related documents by an Intertek recognized testing laboratory. This Certificate is only confirmable in conjunction with equipment being listed in AC 150/5345-53, Appendix 3, Addendum, as currently published by the FAA. The certification is not valid for a product modified with non-OEM replacement parts or non-production components.

L-850(L) – Lights, Runway, Inpavement (AC 150/5345-46D)				
Manufacturer	Type	Class	Style	Manufacturer's Catalog Number
OCEM Airfield Technology	T T	1, 2 1, 2	3 3	LIRC-F-TS-1P-X-X-X(535); LIRC-F-TM-1P-X-X-X (535); LIRL-F-TS-1P-X-X (532); LIRL-F-TM-1P-X-X (532)

NOTE: (535) 150.3399 Red LED; (532) 150.4044 Red LED

Equipment meets the requirements of FAA Engineering Brief No. 67D additional requirements for "Light Sources Other Than Incandescent and Xenon for Airport and Obstruction Lighting Fixtures" dated March 6, 2012.

- 1. This Equipment requires continuing validation in accordance with the requirements of AC 150/5345-53, and the Intertek Airport Lighting Equipment Certification Program.
- 2. Product tested and Report issued by: OCEM Airfield Technology; EuroTest, CERMET

(A) Report No: UT-RP-0240; EMC06 27210-130254; (B) Date of Report: 7/2013; 7/2013; 7/2013 1300773BRI

NOTE: PLEASE REVIEW, AND ADVISE ADMINISTRATOR AT INTERTEK IMMEDIATELY IF DATA, AS SHOWN, NEED TO BE

CORRECTED.

Approved for Certification by:

Jeremy N Downs, P.E., Program Administrator Date: September 30, 2013