

PROGRAM ADMINISTRATOR DEPARTMENT ALECP INTERTEK 3933 U.S. ROUTE 11 CORTLAND, NY 13045-0950

OCEM Airfield Technology a division of Energy Technology S.r.l. Via 2 Agosto 1980, 11 40016 San Giorgio di Piano Bologna - Italy **REVISION DATE: June 24, 2013** 

ORIGINAL ISSUE DATE: June 19, 2013

Recertification due: April 2021

An Activity Sponsored and Administered by Intertek

## AIRPORT LIGHTING EQUIPMENT CERTIFICATION PROGRAM

## CERTIFICATE OF CONFORMANCE

The product described below is hereby approved for listing in the next issue of the Federal Aviation Administration (FAA) Advisory Circular (AC) 150/5345-53, Appendix 3 Addendum "Airport Lighting Equipment Certification Program. The approval is based on successful completion of tests in accordance with the specifications listed in, and the requirements for approval described in the Advisory Circular, and the reporting to the Program Administrator the results of such tests, accompanied by related documents by an Intertek recognized testing laboratory. This Certificate is only confirmable in conjunction with equipment being listed in AC 150/5345-53, Appendix 3, Addendum, as currently published by the FAA. The certification is not valid for a product modified with non-OEM replacement parts or non-production components.

L-850 – Lights, Runway, Inpavement (AC 150/5345-46D)				
Manufacturer	Туре	Class	Style	Manufacturer's Catalog Number
OCEM Airfield Technology	D D D D E T	1, 2 1, 2 1, 2 1, 2 1, 2 1, 2 1, 2	3 3 3 3 3 3	SLRE-A-GRP-XP-200-O-F (520) SLRE-A-GXP-1P-100-O-F (520) SLRE-A-RPG-XP-200-O-F (520) SLRE-A-RPR-XP-200-O-F (520) SLRE-A-XPG-1P-100-O-F (520) SLTH-A-ST-200-O-F (520) RCLF-F-TM-100-1P-X-F (520)
NOTE: (520) 760.2190 105W				

- 1. This Equipment requires continuing validation in accordance with the requirements of AC 150/5345-53, and the Intertek Airport Lighting Equipment Certification Program.
- 2. Product tested and Report issued by: OCEM Airfield Technology

(A) Report No: UT-RP-0233

(B) Date of Report: 4/2013

Approved for Certification by:

NOTE: PLEASE REVIEW, AND ADVISE ADMINISTRATOR AT INTERTEK IMMEDIATELY IF DATA, AS SHOWN, NEED TO BE CORRECTED.

Jeremy N Downs, P.E., Program Administrator

Date: June 24, 2013